

*If you are using a printed copy of this procedure, and not the on-screen version, then you **MUST** make sure the dates at the bottom of the printed copy and the on-screen version match. The on-screen version of the Collider-Accelerator Department Procedure is the Official Version. Hard copies of all signed, official, C-A Operating Procedures are available by contacting the ESSHQ Procedures Coordinator, Bldg. 911A*

C-A OPERATIONS PROCEDURES MANUAL

15.6.6 Procedure for Replacing Feedback Amps

(RF Group Procedure RF006)

Note: This document was formerly a C-A Group Procedure. The content of the group procedure was reviewed by the Technical Supervisor. All approvals and/or issue dates of the original group procedure are maintained for present use.

Hand Processed Changes

<u>HPC No.</u>	<u>Date</u>	<u>Page Nos.</u>	<u>Initials</u>
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Approved: _____
Collider-Accelerator Department Chairman Date

A. Zaltsman

RF Group
Group Procedure RF006
Original Issue Date: 06/25/1998
Revision 00

BROOKHAVEN NATIONAL LABORATORY

Procedure for Replacing _____ Feedback Amplifier

Any time the RF Group is going to replace a feedback amplifier or a tube from a feedback amplifier from the ATS ring the following steps should be followed.

Head of Safety: _____

Check Each Step

- | | |
|--|-------|
| 1. Lock out and tag out system | _____ |
| 2. Disconnect all the cables | _____ |
| 3. Take out Feedback amplifier | _____ |
| 4. Install new one | _____ |
| 5. Reconnect all the cables | _____ |
| 6. Remove LO/TO | _____ |
| 7. Test Feedback amplifier before leaving ring | _____ |